
Which coupons D_{66} actually depends on
all four
D_{66} (N mm)
15
10
5
0
drop longitudinal
drop transverse-raw
drop 45deg
drop twist
longitudinal + transverse-raw
longitudinal + 45deg
transverse-raw + 45deg
transverse-raw + twist
45deg + twist