

SM2260 F/W Release Note

FW Package	MP Tool	ISP	Note
	Version	Version	
C2.0.0	V3.0.1	C2.2.0	Enable Intel L06B.
C2.0.0	V3.U.1	C2.2.0	Update DRAM parameters.
			Enable multi-port initialization on 4-port Tester.
C1.0.5	V2.2.2	C1 0 F	Initial FW release, including MPTool and EZTool.
C1.0.5	V Z.Z.Z	C1.0.5	Support Micron L06B.

Note:

- 1. F/W and ISP update is recommended.
- 2. History # is denoted by "Version-Date".

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.

[1] 8/30/2016