

Part Specification Sheet - AV Tray Mount

Controlled Doc #: SPEC-2026-001

SKU #: AV-TRAY-100
Part #: AV-TRAY-100
Part Name: AV Tray Mount

Materials

Materials and Components

Qty	Part Number	Description	Material Spec	UOM	Lot/Heat	CoC	Material Cert	Notes
1	AL-6061-PLATE	6061-T6 aluminum plate with retained heat certification	AMS 4027	EA	Yes	Yes	Yes	Retain certification with the permanent manufacturing record.
4	NAS1352C04	Socket head cap screw	NAS1352	EA	Yes	Yes	No	Clean, bag, and protect threads before issue.

CNC Operations

CNC Operations

Seq	Dept	Operation	Program	Prog Rev	Machine	Fixture	Setup	Cycle	Prove-out	Source ID
10	CNC	Machine datum A with a deliberately long instruction that must wrap without clipping	AVTRAY-OP10	E	3-axis mill	FX-AV-02	25	8	Yes	00000000-0000-0000-0000-0000000088
20	CNC	Machine datum B with a deliberately long instruction that must wrap without clipping	AVTRAY-OP20	C	3-axis mill	FX-AV-02	12	6	No	00000000-0000-0000-0000-0000000089

QC Standards

QC Standards

Characteristic	Nominal	Tol	Lower	Upper	Unit	Method	Gage	Phase	Coverage	Sample	Ac	Re	Hard Stop	Reference
KC-01 machined feature	1.251	+/-0.005	1.246	1.256	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 1; this controlled reference must wrap cleanly
KC-02 machined feature	1.252	+/-0.005	1.247	1.257	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 2; this controlled reference must wrap cleanly
KC-03 machined feature	1.253	+/-0.005	1.248	1.258	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 3; this controlled reference must wrap cleanly
KC-04 machined feature	1.254	+/-0.005	1.249	1.259	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 4; this controlled reference must wrap cleanly

Characteristic	Nominal	Tol	Lower	Upper	Unit	Method	Gage	Phase	Coverage	Sample	Ac	Re	Hard Stop	Reference
KC-05 machined feature	1.255	+/-0.005	1.250	1.260	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 5; this controlled reference must wrap cleanly
KC-06 machined feature	1.256	+/-0.005	1.251	1.261	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 6; this controlled reference must wrap cleanly
KC-07 machined feature	1.257	+/-0.005	1.252	1.262	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	Yes	DWG-AV-100 Rev D, feature zone 7; this controlled reference must wrap cleanly
KC-08 machined feature	1.258	+/-0.005	1.253	1.263	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 8; this controlled reference must wrap cleanly
KC-09 machined feature	1.259	+/-0.005	1.254	1.264	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 9; this controlled reference must wrap cleanly
KC-10 machined feature	1.260	+/-0.005	1.255	1.265	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 10; this controlled reference must wrap cleanly
KC-11 machined feature	1.261	+/-0.005	1.256	1.266	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 11; this controlled reference must wrap cleanly
KC-12 machined feature	1.262	+/-0.005	1.257	1.267	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 12; this controlled reference must wrap cleanly
KC-13 machined feature	1.263	+/-0.005	1.258	1.268	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 13; this controlled reference must wrap cleanly
KC-14 machined feature	1.264	+/-0.005	1.259	1.269	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	Yes	DWG-AV-100 Rev D, feature zone 14; this controlled reference must wrap cleanly
KC-15 machined feature	1.265	+/-0.005	1.260	1.270	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 15; this controlled reference must wrap cleanly
KC-16 machined feature	1.266	+/-0.005	1.261	1.271	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 16; this controlled reference must wrap cleanly
KC-17 machined feature	1.267	+/-0.005	1.262	1.272	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 17; this controlled reference must wrap cleanly
KC-18 machined feature	1.268	+/-0.005	1.263	1.273	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 18; this controlled reference must wrap cleanly
KC-19 machined feature	1.269	+/-0.005	1.264	1.274	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 19; this controlled reference must wrap cleanly

Characteristic	Nominal	Tol	Lower	Upper	Unit	Method	Gage	Phase	Coverage	Sample	Ac	Re	Hard Stop	Reference
KC-20 machined feature	1.270	+/-0.005	1.265	1.275	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 20; this controlled reference must wrap cleanly
KC-21 machined feature	1.271	+/-0.005	1.266	1.276	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	Yes	DWG-AV-100 Rev D, feature zone 21; this controlled reference must wrap cleanly
KC-22 machined feature	1.272	+/-0.005	1.267	1.277	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 22; this controlled reference must wrap cleanly
KC-23 machined feature	1.273	+/-0.005	1.268	1.278	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 23; this controlled reference must wrap cleanly
KC-24 machined feature	1.274	+/-0.005	1.269	1.279	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 24; this controlled reference must wrap cleanly
KC-25 machined feature	1.275	+/-0.005	1.270	1.280	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 25; this controlled reference must wrap cleanly
KC-26 machined feature	1.276	+/-0.005	1.271	1.281	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 26; this controlled reference must wrap cleanly
KC-27 machined feature	1.277	+/-0.005	1.272	1.282	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 27; this controlled reference must wrap cleanly
KC-28 machined feature	1.278	+/-0.005	1.273	1.283	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	Yes	DWG-AV-100 Rev D, feature zone 28; this controlled reference must wrap cleanly
KC-29 machined feature	1.279	+/-0.005	1.274	1.284	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 29; this controlled reference must wrap cleanly
KC-30 machined feature	1.280	+/-0.005	1.275	1.285	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 30; this controlled reference must wrap cleanly
KC-31 machined feature	1.281	+/-0.005	1.276	1.286	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 31; this controlled reference must wrap cleanly
KC-32 machined feature	1.282	+/-0.005	1.277	1.287	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 32; this controlled reference must wrap cleanly
KC-33 machined feature	1.283	+/-0.005	1.278	1.288	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 33; this controlled reference must wrap cleanly
KC-34 machined feature	1.284	+/-0.005	1.279	1.289	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 34; this controlled reference must wrap cleanly

Characteristic	Nominal	Tol	Lower	Upper	Unit	Method	Gage	Phase	Coverage	Sample	Ac	Re	Hard Stop	Reference
KC-35 machined feature	1.285	+/-0.005	1.280	1.290	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	Yes	DWG-AV-100 Rev D, feature zone 35; this controlled reference must wrap cleanly
KC-36 machined feature	1.286	+/-0.005	1.281	1.291	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 36; this controlled reference must wrap cleanly
KC-37 machined feature	1.287	+/-0.005	1.282	1.292	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 37; this controlled reference must wrap cleanly
KC-38 machined feature	1.288	+/-0.005	1.283	1.293	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 38; this controlled reference must wrap cleanly
KC-39 machined feature	1.289	+/-0.005	1.284	1.294	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 39; this controlled reference must wrap cleanly
KC-40 machined feature	1.290	+/-0.005	1.285	1.295	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 40; this controlled reference must wrap cleanly
KC-41 machined feature	1.291	+/-0.005	1.286	1.296	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	No	DWG-AV-100 Rev D, feature zone 41; this controlled reference must wrap cleanly
KC-42 machined feature	1.292	+/-0.005	1.287	1.297	in	CMM inspection	CMM-01	FINISH	100%	1	0	1	Yes	DWG-AV-100 Rev D, feature zone 42; this controlled reference must wrap cleanly