

Main GUI (1)

Graphical User Interface, allows visualizing states and configuring application

Measurement Routine (2)

Custom defined routine for conducting the measurement. Running in own thread

HW Python Modules (3-5)

(4*, 5*): Python modules within own process for controlling external hardware (3): The prober module for controlling the probing system (chuck, optical movement system)

Other Python Modules

Python Modules for e.g., data handeling, post processing or file handeling

External Interface (API)

API or SDK for interfacing external hardware.