Core64 Logic Board (LB) v0.4 Errata.docx

Updated 2021-01-12

FRONT SIDE

Silkscreen error. 3V3 should be 5V0.

Q22 footprint is wrong

Q21 footprint is wrong

Silkscreen error, should be, left-to-right: 1P 1N 2P 2N