Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

PR001 10/08/2024

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Dwath	5. Fatal Case No
F - Fatal Injury	17 - Machinery	09/28/2024 7:55 AM	10/05/2024 4:16 PM	FAI-F001263-1

6. Mine Information
- **a) Mining Company Name:** ACI Tygart Valley
- **b) Mine Name:** Leer Mine
- **c) Parent of Mining Company:** Arch Resources Inc

7. Mine Location Information			8. Mine ID Number	9. Union
a) City	b) County	c) State		
Grafton	Taylor	WV	46-09192	No

10. Primary Mineral Mined	11. Number of Employees				
	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
Bituminous Coal Underground Mining	574	476		50	48

12. Contractor Name	13. Contractor Union	14. Contractor ID Number

15. Contractor Address			
a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees				
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident		18. Number of Persons Unaccounted for	
a) Mine Employees	b) Contractor Employees	a) Mine Employees	b) Contractor Employees
172			

19. Accident Location	20. Mining Height
08 - Retreat Mining	8 Feet 0 Inches

21. Nonfatal Injuries	22. Fatal Injuries
	1

23. Victims Information

Colton Walls

a) First Name	a) MI	a) Last Name	b) Age	c) Regular Job Title	d) Activity at Time of Accident	Employee
Colton		Walls	34	Electrician	Shieldman	Mine Employee

24. Mining Experience

a) Total Experience	b) Experience at the Mine	c) Experience at the Activity at the Time of the Accident	d) Experience with Contractor
14 Years 28 Weeks 0 Days	7 Years 16 Weeks 0 Days	2 Years 26 Weeks 0 Days	Years Weeks Days

25. Autopsy Performed	If Yes, Location
Yes	Charleston, WV

26. Mine Telephone No.
(304) 265-9700

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)
During the process of realigning some longwall shields, a miner received injuries on an active longwall panel. The miner died from his injuries on October 4, 2024.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding thecause of the accident.

28. Equipment Manufacturer	29. Model

30. District	32. Field Office	33. Event Number
C0300 - Morgantown District	C0303 - Bridgeport WV Field Office	F001263

34. Accident Investigator

First Name	MI	Last Name
Ronald	L.	Sheets

35. MSHA Person Notified

First Name	MI	Last Name	Date/Time Notified
Stephen		Wilt	09/29/2024 8:07 AM

36. Type of Report	37. Name of Preparer	
	Full Name	Date Prepared
Initial	Michael P Stark	10/07/2024

38. Reason for Amendment