Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

PR001 03/05/2026

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
F - Fatal Injury	05 - Falling, Rolling or Sliding Rock /Material	03/03/2026 1:08 PM	03/03/2026 02:00 PM	FAI-F01E9A8-1

6. Mine Information
- **a) Mining Company Name:** North American Silica Sand, LLC
- **b) Mine Name:** North American Silica Sand, LLC
- **c) Parent of Mining Company:** Ignacio Martinez

7. Mine Location Information			8. Mine ID Number	9. Union
a) City	b) County	c) State		
NEW BRAUNFELS	Atascosa	TX	41-05470	

10. Primary Mineral Mined	11. Number of Employees				
	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
Industrial Sand, N.E.C.	5			5	

12. Contractor Name	13. Contractor Union	14. Contractor ID Number
Renteria Construction		C9701

15. Contractor Address			
a) City	b) County	c) State	d) Zip Code
San Antonio		TX	78250

16. Number of Contractor Employees				
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
10			10	

17. Number of Persons in Mine at Time of Accident		18. Number of Persons Unaccounted for	
a) Mine Employees	b) Contractor Employees	a) Mine Employees	b) Contractor Employees
5	10		

19. Accident Location	20. Mining Height
30 - Mill/Prep Plant	Feet Inches

21. Nonfatal Injuries	22. Fatal Injuries
	1

23. Victims Information

Leandro Castro

a) First Name	a) MI	a) Last Name	b) Age	c) Regular Job Title	d) Activity at Time of Accident	Employee
Leandro		Castro	63	Concrete Construction	Concrete Construction	Contractor Employee

24. Mining Experience

a) Total Experience	b) Experience at the Mine	c) Experience at the Activity at the Time of the Accident	d) Experience with Contractor
Years Weeks 2 Days	Years Weeks 2 Days	40 Years Weeks Days	2 Years 26 Weeks

25. Autopsy Performed | **If Yes, Location**

26. Mine Telephone No.
(210) 542-3293

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)
A contractor died after a concrete retaining wall collapsed into the excavated trench below crushing him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding thecause of the accident.

28. Equipment Manufacturer	29. Model

30. District	32. Field Office	33. Event Number
M5000 - Dallas District	M5611 - San Antonio TX Field Office	F01E9A8

34. Accident Investigator

First Name	MI	Last Name
Belinda	J	Youngblood

35. MSHA Person Notified

First Name	MI	Last Name	Date/Time Notified
Ronnie		Free	03/03/2026 1:14 PM

36. Type of Report	37. Name of Preparer	
	Full Name	Date Prepared
Initial	Belinda J Youngblood	03/03/2026

38. Reason for Amendment