Α4

А3

A2

A1

A12/D35

A7/D36

A6/D37

A5/D38

A4/D39

ADC_IN4

ADC IN3

ADC_IN2

ADC IN1

ADC IN0

DAC OUT1

USART2 RX

USART2 TX

USART2 RTS

USART2 CTS

PWM

PWM

PWM

PWM

Encoder A Socket A

Encoder B Socket A

BT-UART-TX-P

BT-UART-RX-P

Right Motor+ (Socket B)

Right Motor- (Socket B)

Left Motor+ (Socket A)

Left Motor- (Socket A)

PWM

PWM

PWM

PWM

A0/D15

A1/D16

A2/D17

A3/D18

RST

ADC_IN10

ADC IN11

ADC_IN12

ADC IN13

C0

C1

C2

СЗ

RST

Reset

Button

LedBT

LedG

41

C15 C14 B4 B3 A15 A14 A13 A0