C15 C14 B4 B3 A15 A14 A13 A0

OSC3 OSC3 SPI3 SPI3 SPI3 JTCK JTMS

IN MISO SCK NSS SWC SWDI

OUT

A4/D39

ADC IN0

USART2 CTS

PWM

QEncACnt-INT-LMotor(SktA) BT-UART-RTS

RST

RST