


These are the new markers for the cars. We opted to cut the points off of the triangle because the CV system was occasionally seeing the inner triangle as a different shape, and it was causing problems with the heading and direction of the cars.



To make the markers, they were printed out on paper and attached to thicker cardstock using a light epoxy. This increases the rigidity and longevity of the markers as they don't bend or wrinkle over time. Included below is a picture of all three markers on the cars while we're testing them.

