

MITx: 15.071x The Analytics Edge

■Bookmarks

Final Exam > Final Exam > OPTIMAL PRODUCTION SCHEDULING

■ Bookmark

- Unit 1: An Introduction to Analytics
- ► Entrance Survey
- Unit 2: Linear Regression
- Unit 3: Logistic Regression
- Unit 4: Trees
- Unit 5: Text Analytics
- Unit 6: Clustering
- KaggleCompetition
- Unit 7: Visualization
- Unit 8: Linear Optimization
- Exit Survey
- Unit 9: IntegerOptimization

OPTIMAL PRODUCTION SCHEDULING

Falcon Die Casting Company (FDC) is an automotive parts manufacturer based in the United States. FDC uses an innovative method of high volume *die casting*, a metal casting process that is characterized by forcing molten metal under high pressure into a mold cavity. Due to the strength of their method, FDC recently received a long-term contract from a major automobile manufacturer to produce the five key die cast items used in most of their automobiles.

The automobile manufacturer has provided FDC with their weekly demand for the five parts:

Part	Weekly Demand
1	2,450
2	2,100
3	2,800
4	2,800
5	1,960

FDC has five different machines that can be used to produce the parts, but each machine can only produce certain parts (and each machine can only produce one part at any given moment in time). Additionally, the number of parts that can be produced in one hour varies by machine and part. For example, Part 1 can only be produced on Machines 1 and 2. FDC can produce 40 units per hour of Part 1 on Machine 1, but only 35 units per hour of Part 1 on Machine 2. All of this data is given in the following table (a blank entry means the part can't be produced on the machine):

	Machine 1	Machine 2	Machine 3	Machine 4	Machine 5	
--	-----------	-----------	-----------	-----------	-----------	--

▼ Final Exam

Final Exam

Final Exam due Jul 05, 2016 at 00:00 UTC

Part 1	40	35			
Part 2		25	30	35	
Part 3				50	
Part 4	60				60
Part 5			45		50

Production takes place continuously Monday through Friday, for a total of 120 hours of production. Forty of these 120 hours (the overnight hours on each of the five days) are ideally used for preventative maintenance and experiementation with new techniques, so using machines during these hours for production is considered overtime. The remaining 80 hours per week are not considered overtime hours.

In this problem, we'll help the production manager use optimization to determine the number of non-overtime and overtime hours to use each machine to manufacture each part (for a single week). Machines can be assigned a non-integer number of hours producing a part over the course of a week. The production manager's goal is to minimize the total number of overtime machine-hours used during the week, while still making sure the factory is producing enough parts to meet the weekly demand of the automobile manufacturer.

Problem 1 - The Decision Variables

(2/2 points)

As mentioned above, the production manager needs to decide the number of non-overtime and overtime hours to use each machine to manufacture each part (for a single week). These are the decisions for our optimization problem.

How many decision variables will there be in your optimization formulation? (HINT: Remember that not all parts can be produced on all machines, so you might not need a decision variable for each part/machine pair.)

20 **Answer:** 20

You should have two decision variables (the number of non-overtime and overtime hours) for each feasible part/machine pair. There are 10 different part/machine possibilities (non-empty cells in the table in the introduction), so there are 20 decision variables.

You have used 1 of 2 submissions

Problem 2 - The Decision Variables

(1/1 point)

What type of decision variables should be used in the optimization formulation?

- Continuous variables allowed to take negative or non-negative values
- Continuous variables limited to non-negative values



- Binary variables
- Integer variables allowed to take negative or non-negative values
- Integer variables limited to non-negative values

EXPLANATION

Continuous variables should be used, as the number of hours per week to use a machine to produce a part can be fractional. However, the number of hours per week cannot be negative.

You have used 1 of 1 submissions

Problem 3 - The Objective

(1/1 point)

The objective of the production manager is to minimize the total number of overtime machine-hours that need to be used. How many of the decision variables defined in Problem 1 have to do with the overtime shifts?

10 **✓ Answer:** 10

EXPLANATION

One of the decision variables for each machine/part pair indicates the number of overtime hours used by that machine to produce that part. You will want to minimize the sum of these decision variables.

You have used 1 of 2 submissions

Problem 4 - Demand Constraints

(4/4 points)

The production manager needs to be sure that the weekly demand is met for each part. If we decide to produce Part 1 on Machine 1 for 20 non-overtime hours and 4 overtime hours and to produce Part 1 on Machine 2 for 32 non-overtime hours and 0 overtime hours, how many units of Part 1 will we produce?

2080 **✓ Answer:** 2080

EXPLANATION

Machine 1 produces Part 1 at 40 units/hour, so over 24 hours it will produce 40*24=960 units. Machine 2 produces Part 1 at 35 units/hour, so over 32 hours it will produce 35*32=1120 units. In total we will produce 960+1120=2080 units of Part 1.

Denote the total number of units of Part 1 produced by N. In our optimization formulation, we need to include a constraint that N is at least how much?

Answer: 2450 2450 **EXPLANATION** We need to make sure that N is at least the demand for Part 1. You have used 1 of 3 submissions Problem 5 - Capacity Constraints (1/1 point) No machine can work for more than 80 non-overtime hours or 40 overtime hours. How many total constraints do we need to add to the model to ensure this requirement is met? 10 Answer: 10 **EXPLANATION** For each of the 5 machines, we need one constraint to limit the total non-overtime hours to be no more than 80 and another constraint to limit the total overtime hours to be no more than 40. This is a total of 2*5=10 constraints. You have used 1 of 2 submissions Problem 6 - Solving the Model (4/4 points) Set up and solve this optimization problem in the spreadsheet software of your choice (Excel, LibreOffice, or OpenOffice). Remember to define all of your decision variables, your objective, and your constraints. How many overtime machine-hours are used to produce the parts?

Answer: 0

The optimal objective function value is 0, meaning that no overtime machine-hours are used to produce the parts.

You have used 1 of 3 submissions

Problem 7 - Robustness to Machine Failure

(2/2 points)

FDC wants to be robust to machine failure; that is, they want to still be able to meet the demand for all parts even if one of the machines goes offline for the entire week. Re-solve your model five times, once with each machine removed. Which machines could go offline for the whole week (assuming the other four machines remain fully operational) and FDC would still be able to meet customer demand? Select all that apply.

V	Machine 1	~	

/

V	Machine 3	~

Machine	4
WIGCIIIIC	

V	Machine 5	
	Machine	



EXPLANATION

This can be determined by re-solving the model five times, each time forcing one of the machines to have 0 hours.

You have used 2 of 2 submissions

Problem 8 - Quality Control

(4/4 points)

Unfortunately, the FDC discovered that a significant percentage of the parts being produced are not at a quality level demanded by the customer. FDC's industrial engineers developed "yield factors", which are quite accurate in predicting the proportion of parts that meet customer quality specifications. The yield factors are as follows:

Part 1 = 60%

Part 2 = 55%

Part 3 = 75%

Part 4 = 65%

Part 5 = 60%

So, for example, only 60% of the Part 1 units produced meet the necessary quality standards, regardless of the machine that produced those units. FDC needs to ensure that they are producing enough high quality parts to meet the weekly customer demand.

Adjust your optimization formulation to account for this requirement by requiring the number of high-quality parts produced to exceed the demand. You should still minimize the number of overtime machine-hours that are used.

How many overtime machine-hours are now used in the optimal solution?

44.157 **✓ Answer:** 44.157

Which machines are used at their full overtime capacity (all 40 overtime hours) in the optimal solution? Select all that apply.

Machine 1	
Machine 2	
Machine 3	
Machine 4	✓
Machine 4 Machine 5	✓

In the five demand constraints, either the number of products produced could be multiplied by the appropriate yield factors (to account for the number of high quality parts produced), or the amount of demand required could be divided by the appropriate yield factors (to account for the increased number of parts needed).

You have used 1 of 3 submissions

Problem 9 - Sensitivity Analysis

(1/1 point)

FDC's automotive partner proposes a 100 unit increase in the demand for Part 3, in exchange for compensation that FDC thinks is worth using up to 10 machine-hours of overtime (they would accept this proposal if it cost them less than 10 machines hours of overtime to produce the extra parts). Should FDC accept this proposal? Use your model from Problem 8 (the model that takes into account yield factors) when making the decision.

- Yes ✔
- No
- It is unclear whether they should accept this proposal

From changing the demand and re-solving the model, we see that the number of machine-hours of overtime increases by 2.8, less than the 10 machine-hours of value that the company derives from the proposal. Therefore the proposal should be accepted by FDC.

You have used 1 of 1 submissions

ACKNOWLEDGEMENTS

This problem is based on the case study "Production Scheduling at Falcon Die Casting" by B. Madhu Rao and Jeroen Belien, INFORMS Transactions on Education 15(1), p.154-155, 2014.

© All Rights Reserved



© edX Inc. All rights reserved except where noted. EdX, Open edX and the edX and Open EdX logos are registered trademarks or trademarks of edX Inc.















