







## Notes:

- Pins 0 to 15 can be PWM, depending on the firmware it varies how many can be used at the same time
- In ESPinos Rev. A, the RX and TX markings are inverted by mistake

