GUIEDANCE SEQUENCE TROUBLESHOOTING VIM

| NO | TROUBLE | | ACTION | STANDAR |
|----|--|---|---------------------|--------------|
| 1 | MARKING NO CENTER TO POINT CHECKING | 1 | Cek Base Jig | posisi fix |
| | | 2 | Cek posisi kamera | posisi fix |
| | | 3 | Cek File Program | Sesuai SOP |
| 2 | STANDARD VALUE DOWN | 1 | Cek Lighting (Lamp) | Normal |
| | | 2 | Cek File Program | Sesuai SOP |
| | | 3 | Cek area Jig | clear area |
| | | 1 | | |
| | | 2 | | |
| 3 | | 3 | | |
| | | 4 | | |
| | | 5 | | |
| | | 6 | | |
| 4 | | 1 | | |
| | | 2 | | |
| | | 3 | | |
| | | 4 | | |
| | | 5 | | |
| Ę | | 1 | | |
| | | 2 | | |
| 5 | | 3 | | |
| | | 5 | | |
| | | 1 | | |
| 6 | | 2 | | |
| | | 3 | | |
| | | 4 | | |
| | | 5 | | |
| | | 1 | | |
| | | 2 | | |
| | I | | | |

| 7 | | 3 | |
|----|--|---|--|
| | | 4 | |
| | | 5 | |
| | | 1 | |
| 8 | | 2 | |
| 0 | | 3 | |
| | | 4 | |
| 9 | | 1 | |
| | | 2 | |
| 9 | | 3 | |
| | | 4 | |
| | | 1 | |
| | | 2 | |
| 10 | | 3 | |
| 10 | | 4 | |
| | | 5 | |
| | | 6 | |
| | | 1 | |
| | | 2 | |
| 11 | | 3 | |
| | | 4 | |
| | | 5 | |
| | | 1 | |
| | | 2 | |
| 12 | | 3 | |
| | | 4 | |
| | | 5 | |
| | | 1 | |
| | | 2 | |
| 13 | | 3 | |
| | | 4 | |
| | | 5 | |
| | | 1 | |
| | | 2 | |
| | | | |

| 14 | | 3 | |
|----|--|---|--|
| | | 4 | |
| | | 5 | |
| | | 1 | |
| | | 2 | |
| 15 | | 3 | |
| | | 4 | |
| | | 5 | |
| | | 1 | |
| | | 2 | |
| 16 | | 3 | |
| | | 4 | |
| | | 5 | |