

INSTRUKSI KERJA SAAT TEGANGAN TURUN *WORKING INSTRUCTIONS WHEN VOLTAGE FALLS*

1. Melakukan pengecekan tegangan pada setiap panel produksi
Check the voltage on each production panel
2. Cek dan ukur voltase menggunakan **Tang Ampere / Multytester**
*Check and measure the voltage using **Ampere Pliers / Multitester***
3. Jika tegangan listrik di **bawah batas normal / 360V**, matikan beberapa mesin yang riskan pada tegangan rendah
*If the power voltage is below the **normal limit / 360V**, turn off some machines risky at low voltage*

Beberapa mesin yang riskan pada tegangan rendah
Some machines are risky at low voltage

- * **COMELZ MACHINE**
- * **LECTRA MACHINE**
- * **SEWING COMPUTER**

4. Jika mesin sudah terpasang **AVR**, maka tidak perlu mematikan mesin tersebut
*If the machine has **AVR** installed, there is no need to turn off the machine*
5. Apabila hasil pengecekan tegangan drop terlalu banyak atau **kurang dari 350V**, segera konfirmasi ke **team facility** jika memungkinkan generator dinyalakan
*If the results of checking the voltage drop are too much or **less than 350V**, Immediately confirm with the **facility team** if it is possible to turn on the generator*