

(a) Posterior view
(b) Left lateral view
(c) Error by class
ALL
PLL
LF
ISL
SSL
ITL
CL
GCZ
GCZ-RL
2
4
6
8
MAE on S03 L4 (mm)
ISL
SSL
ITL
CL
Expert reference
GCZ landmark
GCZ-RL landmark