No. 002/SRT/01/2022

SERVICE REPORT				
Product:	Merk/Type:	Serial No:	Version:	Date: Celasa 18 / 01 / 2022
Hematology Analyzer	Norma / 1 con 3	N030 H17022	0.4.922.0	Travel Time (B-F): 07 h m
7711419201		74.8		Time Work Started: \O h 00 m
		* A.*		Time Work Finished: 18 h 00 m
Customer:		Address/Ph Number:		
RSUD Mos Amsyor		JI. Rimah sakit No. 1 Kasengan		
Job Title: Install		Repair Update		Update
ul-	Training	Maintenance		Refurbishment
Action Bry Injector: Setting Ni Opto Senser, test ouch dan Dv1) Nump: mengganti valve A L H dengan manifeldinga - Mengganti opon wash head (retak): Julankan hambias! 4 a C				
Remarks: Perbaikon alat Sideh relesur Cspore ports yang tuscus ementara dryanti pavai milik pt. TOPA? Alat O.K., Host ac O.K. Reggent Connector, maintenances kit List Spareport yang perso dryanti Valve AlH, Manifold vaive, open wish ha				
Status After Service			Operational	☐ To be Monitored
Reported by TOF BORNEO	Engineer A Little UTAMA Lahmyt Ramudher			Acknowledged and Approved by Customer: dr. SUMAR OPK NIP. 19770124 200804 2 015