No. 003 /SRT/01/2022

Product:	Merk/Type:	Serial No:	Version:	Date: (elosa 10/0/12022
ESP Analyzer	ALCOR LISED	02265		Travel Time (B-F): h m
Caagulation Analyzer	Succede F / SF-8050			Time Work Started: h & m
Analyzer	socceder / species	G&1200	2.1	Time Work Finished: 13 h 60 m
Customer: Address/Ph Number:				
Customer:		JI. Rimah Sakt No. 1 Kasenagn		
RSUD Mas Amsyar		0. Pallall 24		
Job Title: Install		Repair Update		
Training		Maintenance		Refurbishment
Report Fault: Maintenance Ruto				
Action (SED Jalanum Cleaning, membershum body glat Jalanum ac Lui LZ tes samper posien.				
Jalankan ac Lu 1 22, ees ramper posiers.				
Kogulas: ! Jalankan Cleaning, membershkan area kerja alan Cek has. I a C				
Lek hail a				
Remarks: 1SED O.K, hos. 1 ac masik talget pergelaken toter o. K				
legaguesi O.K, Channy sidah dilauwan / Hosi QC O.K				
(Loageras, o. x / cearing > carr) or (auctor)				
Status After Service	: Operations	al Non C	perational	☐ To be Monitored
Reported by Engineer Acknowledged and Approved by Customer:				
TOPAZ				
BORNEO UTAMA Rahmat Ramadhen NIP 19770-12 200604 2 015				
Rahmat Kemadhen NIP. 1977012+2006042015				
		1 1		N year I