

PC Simulator for Semi-integrated Solution (WINTSI)

RELEASE NOTE 0008-08180-0302

Release Notes

WINTSI 3.02

• Fix a problem of sending empty request when ECR request buffer is up to 512 (for serial only)