```
[calibration_status:
 display: FAIL
 probe: FAIL
components_tested:
 imaging_modes:
  2D: FAIL
  Doppler: PASS
  M-Mode: FAIL
 network_connectivity:
  network_status: Connected
  signal_strength: -51 dBm
 power_supply:
  battery_level: 97%
  current: 1.2A
  voltage: 22.1V
 probe_check:
  connection_status: Connected
  frequency_response: 3.5 MHz
  probe_id: L12345
  type: Linear
 temperature_check: "38\xB0C"
error_logs:
- description: Probe disconnected unexpectedly
error_code: E-404
firmware_version: 5.3.2
recommendations: Recalibrate probe
system_status: FAIL
test_duration: 2 minutes
test_id: ST-90337
timestamp: '2024-10-29T02:00:14.761750Z']
```

```
[calibration_status:
 display: FAIL
 probe: FAIL
components_tested:
 imaging_modes:
  2D: FAIL
  Doppler: FAIL
  M-Mode: PASS
 network_connectivity:
  network_status: Connected
  signal_strength: -79 dBm
 power_supply:
  battery_level: 82%
  current: 1.3A
  voltage: 23.7V
 probe_check:
  connection_status: Connected
  frequency_response: 3.5 MHz
  probe_id: L12345
  type: Convex
 temperature_check: "36\xB0C"
error_logs: []
firmware_version: 5.3.2
recommendations: Recalibrate probe
system_status: FAIL
test_duration: 1 minutes
test_id: ST-63030
timestamp: '2024-10-29T02:06:51.723296Z']
```

```
[calibration_status:
 display: PASS
 probe: PASS
components_tested:
 imaging_modes:
  2D: FAIL
  Doppler: PASS
  M-Mode: PASS
 network_connectivity:
  network_status: Disconnected
  signal_strength: -58 dBm
 power_supply:
  battery_level: 86%
  current: 1.3A
  voltage: 23.7V
 probe_check:
  connection_status: Disconnected
  frequency_response: 7.5 MHz
  probe_id: C78901
  type: Linear
 temperature_check: "37\xB0C"
error_logs: []
firmware_version: 5.3.2
recommendations: Recalibrate probe
system_status: PASS
test_duration: 2 minutes
test_id: ST-63834
timestamp: '2024-10-29T02:07:36.697164Z'
]
```

[calibration\_status:

```
display: PASS
 probe: FAIL
components_tested:
 imaging_modes:
  2D: PASS
  Doppler: PASS
  M-Mode: FAIL
 network_connectivity:
  network_status: Disconnected
  signal_strength: -50 dBm
 power_supply:
  battery_level: 85%
  current: 1.3A
  voltage: 24.6V
 probe_check:
  connection_status: Disconnected
  frequency_response: 7.5 MHz
  probe_id: C78901
  type: Linear
 temperature_check: "37\xB0C"
error_logs:
- description: Probe disconnected unexpectedly
error_code: E-404
firmware_version: 5.3.2
recommendations: Recalibrate probe
system_status: FAIL
test_duration: 5 minutes
test_id: ST-70945
timestamp: '2024-10-29T02:36:23.749216Z'
```

```
[calibration_status:
 display: FAIL
 probe: PASS
components_tested:
 imaging_modes:
  2D: PASS
  Doppler: FAIL
  M-Mode: PASS
 network_connectivity:
  network_status: Disconnected
  signal_strength: -59 dBm
 power_supply:
  battery_level: 81%
  current: 1.3A
  voltage: 24.9V
 probe_check:
  connection_status: Disconnected
  frequency_response: 3.5 MHz
  probe_id: L12345
  type: Convex
 temperature_check: "40\xB0C"
error_logs: []
firmware_version: 5.3.2
recommendations: Recalibrate probe
system_status: PASS
test_duration: 3 minutes
test_id: ST-76628
timestamp: '2024-11-05T16:21:50.907037Z'
]
```

```
[calibration_status:
 display: FAIL
 probe: PASS
components_tested:
 imaging_modes:
  2D: PASS
  Doppler: PASS
  M-Mode: PASS
 network_connectivity:
  network_status: Disconnected
  signal_strength: -77 dBm
 power_supply:
  battery_level: 75%
  current: 1.6A
  voltage: 25.0V
 probe_check:
  connection_status: Disconnected
  frequency_response: 7.5 MHz
  probe_id: L12345
  type: Convex
 temperature_check: "35\xB0C"
error_logs: []
firmware_version: 5.3.2
recommendations: None
system_status: FAIL
test_duration: 4 minutes
test_id: ST-92684
timestamp: '2024-11-05T16:22:57.874647Z'
]
```

[calibration\_status:

```
display: FAIL
 probe: FAIL
components_tested:
 imaging_modes:
  2D: FAIL
  Doppler: FAIL
  M-Mode: FAIL
 network_connectivity:
  network_status: Disconnected
  signal_strength: -71 dBm
 power_supply:
  battery_level: 65%
  current: 1.3A
  voltage: 23.3V
 probe_check:
  connection_status: Connected
  frequency_response: 7.5 MHz
  probe_id: C78901
  type: Linear
 temperature_check: "37\xB0C"
error_logs:
- description: Probe disconnected unexpectedly
error_code: E-404
firmware_version: 5.3.2
recommendations: Recalibrate probe
system_status: FAIL
test_duration: 4 minutes
test_id: ST-91571
timestamp: '2024-11-18T14:20:40.740805Z'
]
```