





		ı		
	ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
	1	95365A503	Cast Iron Precision Acme Round Nut	1
	2	99030A978	1018 Carbon Steel Precision Acme Lead Screw	1
	3	f_router1		1
	4	92949A323	18-8 Stainless Steel Button Head Hex Drive Screw	4
	5	f_gr1		2
	6	6627T111	Stepper Motor	1
	7	4856N11	Spindle Motor	1
	8	new router		1
)	9	spindle bit		1
	10	60355K124	Ball Bearing	1







ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	95365A503	Cast Iron Precision Acme Round Nut	1
2	99030A978	1018 Carbon Steel Precision Acme Lead Screw	1
3	f_router1		1
4	92949A323	18-8 Stainless Steel Button Head Hex Drive Screw	4
5	f_gr1		2
6	6627T111	Stepper Motor	1
7	4856N11	Spindle Motor	1
8	new router		1
9	spindle bit		1
10	60355K124	Ball Bearing	1










	STOY OF THE	AUTHOR:	CLASS:	LAB SECTION:	PREPARI	ED FOR:	
		GROUP 13	MIE 243	LAB 1XX	DRAW	'ING PU	RPOSE
		STUDENT NO.	CNC ROUTER				
	NOTNE BUILD	DATE: 04/12/2024					
		MATERIAL: MATERIAL	PART NO.	XXX		REV.	1
	UNLESS OTHERWISE SPE	ECIFIED, UNITS: MM, DEGREE	SCALE:1:20		SHEET 1	OF 1	



ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	base		1
2	wood top		1
3	gantry(1)		1
4	2391N16	Flange Nut with M20 x 7.50 mm Thread for Fast-Travel Ultra- Precision Lead Screw	2
5	2391N38	Fast-Travel Ultra-Precision Lead Screw	2
6	6495K882	Timing Belt Pulley	2
7	rail and guide		1
8	Belt1-1		1
9	6627T151	Stepper Motor	3
10	23915T85	Tapered-Roller Bearing	4
11	f_subassem2		1
12	7644N14	3.02" Long x 1.77" Wide End Plate for Trade Size L Timing Belt	1
13	Part1^Assem1		1
14	Part2^Assem1		1
15	Part3^Assem1		1
16	leadscrew_motor_lid		2
17	60355K132	Ball Bearing	2
18	belt motor to pulley shaft		1
19	6061K79	Linear Motion Shaft	2
20	6741K43_Emergenc y Stop Panel-Mount Push-Button Switch	Emergency Stop Panel-Mount Push-Button Switch	1

