

AMPTEK, INC.

14 DE ANGELO DRIVE, BEDFORD, MA 01730-2204 U.S.A. TEL + 1 (781) 275 2242 FAX + 1 (781) 275 3470 e-mail: sales@amptek.com WWW: http://www.amptek.com

CAUTION for the A101


This device incorporates an input protection network (see specifications). However, it is not possible to fully protect against high voltage discharge through the input.

Two precautions should be kept in mind:

- 1) The high voltage coupling capacitor should be of sufficient voltage rating that it cannot break down under operating conditions.
- 2) When detector bias is turned on, the rise of high voltage at the detector should be slow enough to prevent large transient currents through the coupling capacitor into the input. This is normally provided for by a high voltage RC Filtering network with components of adequate voltage rating.

In general, it is important to avoid high voltage discharge in any part of the circuit.

EXAMPLE:



Where typically R_1 , $R_2 > 1$ M

R₃ optional additional protection to limit input current, usually less than 1 K

Note: A101

Open collector (Pin 6) should be grounded if not used in order to reduce pick-up, which may cause oscillation.

If the PC-11 is used, remove the pull-up resistor (2k) from Pin 6 to $V_{\rm s}$ and connect Pin 6 directly to Ground.

Care should be taken NOT to connect Pin 6 to V_s instead of connecting it to Ground. This will damage the Pin 6 Output.