Two ways to prevent the rusting of iron are: Oiling, greasing, or painting: By applying oil, grease, or paint, the surface gets a waterproof coating and the moisture and oxygen cannot come into direct contact with the iron article. Hence, rusting is prevented.