
ridge on Sx (purely linear)
degree-2 polynomial in V11-x
mean RMSE ratio minus 1 (negative = arm bette
4
3
2
1
0
10
20
40
80
160
AC solves used for training (n)