

CORNER 0: square corner (-x, -y)



flat on the floor, tag CENTER exactly on the square's corner
any rotation; keep it flat and unwrinkled

DICT_4X4_50 id 0, black square 18.0 cm: print at 100 %, then measure


CORNER 1: square corner (+x, -y)



flat on the floor, tag CENTER exactly on the square's corner
any rotation; keep it flat and unwrinkled

DICT_4X4_50 id 1, black square 18.0 cm: print at 100 %, then measure


CORNER 2: square corner (+x, +y)



flat on the floor, tag CENTER exactly on the square's corner
any rotation; keep it flat and unwrinkled


DICT_4X4_50 id 2, black square 18.0 cm: print at 100 %, then measure

CORNER 3: square corner (-x, +y)



flat on the floor, tag CENTER exactly on the square's corner
any rotation; keep it flat and unwrinkled


ROBOT - FRONT



flat on the robot's back, centered left-right
arrow toward the robot's head
measure its height above the floor (robot standing)

DICT_4X4_50 id 10, black square 18.0 cm: print at 100 %, then measure


OBSTACLE: red chair - FRONT



flat on the top, centered (height 0.45 m)
optional: improves position and heading over detection

DICT_4X4_50 id 20, black square 18.0 cm: print at 100 %, then measure


OBSTACLE: blue chair - FRONT



flat on the top, centered (height 0.45 m)
optional: improves position and heading over detection

DICT_4X4_50 id 21, black square 18.0 cm: print at 100 %, then measure


OBSTACLE: green chair - FRONT



flat on the top, centered (height 0.45 m)
optional: improves position and heading over detection

DICT_4X4_50 id 22, black square 18.0 cm: print at 100 %, then measure


OBSTACLE: yellow chair - FRONT



flat on the top, centered (height 0.45 m)
optional: improves position and heading over detection

DICT_4X4_50 id 23, black square 18.0 cm: print at 100 %, then measure


OBSTACLE: table - FRONT



flat on the top, centered (height 0.75 m)
optional: improves position and heading over detection

DICT_4X4_50 id 24, black square 18.0 cm: print at 100 %, then measure

lens calibration board: 5 x 7 squares of 3.5 cm



tape flat to cardboard; measure one square and set charuco.square_m