

# DATA SHEET

Order code	Manufacturer code	Description				
61-0984	n/a	HCZ-J3A HUMIDITY SENSOR (RC)				

	Page 1 of 6
The enclosed information is believed to be correct, Information may change ±without noticeqdue to product improvement. Users should ensure that the product is suitable for their use. E. & O. E.	Revision A 20/02/2007

Sales: 01206 751166 Sales@rapidelec.co.uk Technical: 01206 835555 Tech@rapidelec.co.uk Fax: 01206 751188 www.rapidonline.com




#### 1 Description

This product specification is applied to the Humidity Sensor Type HCZ-J3. The terminal electrode material uses Lead free solder (Sn/Ag/Cu ). This product is conformity with RoHS directive which means that lead, cadmium, mercury, hexavalent chromium and specific bromine-based flame retardants have not been used.

### 2 Applications


The applications of the component are used in relative humidity measurement, control and display. There are many end products can be used. For example air conditioner, humidifier, dehumidifier, hygrometer, recorder, transmitter...etc.

#### 3 Model no.:



### 4 Configuration & Main parts:

#### 4.1 Configuration: (Units: mm)



Units: mm



Symbol	Specifications	Symbol	Specifications
Α	8.3±0.2	F	0.5±0.1
В	13.5±0.2	G	0.2±0.1
С	4.0±0.5	Н	2.0±0.5
D	15±2	I	5.08±0.3
Е	2.54±0.2	J	10±0.3

## 4.2 Main parts:

No.	Parts	Reference
1	Sensor case	PBT
2	Substrate	Alumina
3	Sensing material	Polymer
4	Electrode	Ag/Carbon
5	Lead frame	Phosphor bronze

#### 5 Electrical characteristics:

### 5.1 General Characteristics:

	Units	Min.	Тур.	Max.
Rated voltage	Vrms	-	-	1
Rated power	mW	1	-	0.2
Operating frequency range	kHz	0.5	1	2
Operating temperature range	$^{\circ}\mathbb{C}$	0	-	60
Operating humidity range	%RH	1	-	90
Impedance range at 60%RH and 25℃**	kΩ	14.2	-	38.5
Humidity accuracy	%RH	-5	-	+5
Hysteresis (40%RH~80%RH)	%RH	-	-	2
Temperature dependence(reference)	%RH/℃	-	0.6	-

<sup>\*\*</sup> Measurement by LCR meter at 1KHz, 1 Vrms(sine wave)

## 5.2 Relative humidity - Impedance – 25°C, 1kHz, 1 Vrms(sine wave)

%RH	20	30	40	50	60	70	80	90
Normal	5,000	920	220	66	22	9.0	4.2	1.9
value (kΩ)	5,000	920	220	00	23	9.0	4.2	1.9

5.3 Relative humidity - Impedance curve is shown in page 5



HCZ-J3

### 6 Mechanical characteristics:

No.	Item	Description	Criteria*
6.1	Shock resistance	Drop down 3 times@80cm	No abnormal
			appearance &
			electrical
			properties
6.2	Vibration resistance	2 hours each in the directions of	No abnormal
		X-Y-Z, at the frequency of 10-55Hz,	appearance &
		and amplitude of 1.5mm	electrical
			properties
6.3	Resistance to	The lead terminal shall be Immersed	No abnormal
	soldering heat	by 3 mm from the substrate for 3	appearance &
		seconds in solder bath of 330±5°C	electrical
			properties
6.4	Strength of	500g@10 seconds in the axial	Secured
	terminations	direction of lead terminal	

## 7 Reliability:

No.	Item	Description	Criteria*
7.1	Heat resistance	1000 hours@70°C	< ±5%RH
7.2	Cool resistance	1000 hours@-30°C	< ±5%RH
7.3	Humidity resistance	1000 hours@60°ℂ, 90%RH	< ±5%RH
7.4	Humidity cycle	Repeat 1000 cycles	< ±5%RH
		One cycle:	
		30 minutes@25℃, <20%RH	
		30 minutes@25℃, >90%RH	
7.5	Temperature cycle	Repeat 100 cycles	< ±5%RH
		Each cycle:	
		30 minutes@-30°C	
		30 minutes@85℃	
7.6	Voltage resistance	3000 hours@1KHz, 1Vrms	< ±5%RH

<sup>\*</sup> The criteria test that the sensors finish the description process after over night under normal temperature and humidity. The test condition is fixed at 25°C, 60%RH by LCR meter at 1KHz, 1 Vrms(sine wave)





### 8 Packaging

- 8.1 HCZ-J3A
  - 8.1.1 100 pieces of sensor to be packed in a bag.
  - 8.1.2 In case of fractional package, the above bag and carton box may not be used.
- 8.2 HCZ-J3B
  - 8.2.1 245 pieces were layed in tray, and 5 trays envelope in bag.
  - 8.2.2 10,000 pieces packed in a shipping carton box (430\*360\*390mm).
  - 8.2.3 In case of fractional package, the above tray and carton box may not be used.
- 8.3 Caution remarks on operation
  - 8.3.1 To avoid direct application of DC voltage on humidity sensor.
  - 8.3.2 To protect sensor from dewfall and drenching.
  - 8.3.3 To avoid any operation of humidity sensors in the following environmental ambient.
    - 8.3.3.1 Salt
    - 8.3.3.2 Inorganic gas Sulfide dioxide, Chlorine, Ammonia etc.
    - 8.3.3.3 Organic gas Alcoholic, Glycols, Aldehydes etc.
  - 8.3.4 Recommended storage condition

Temperature range 10~40°C

Humidity range 90%RH or less

8.3.5 Do not store humidity sensors long period of time in an over 60°C ambient due to some occasion of degradation on sensor housing case.





HCZ-J3

## Impedance table -- %RH VS. Temperature

Unit:KΩ

RH%	5℃	10°C	<b>15</b> ℃	<b>20</b> ℃	<b>25</b> ℃	<b>30</b> ℃	<b>35</b> ℃	<b>40</b> ℃	<b>45</b> ℃	<b>50</b> ℃
20				7200	5000	3600	2500	1800	1300	1100
25	9900	6900	4600	3200	2300	1700	1100	920	600	520
30	4400	3100	2000	1500	920	770	530	430	280	250
35	1900	1400	900	670	450	360	250	210	140	114
40	810	600	430	310	220	170	130	96	74	61
45	420	300	220	160	120	90	71	55	43	35
50	211	150	110	83	66	51	40	31	25	20
55	109	83	62	48	37	29	23	19	15	13
60	63	48	37	29	23	18	15	12	10.3	8.7
65	37	28	22	18	14	12	10	8.1	6.9	5.9
70	22	17	14	12	9.6	8.0	6.8	5.8	4.9	4.3
75	14	12	9.4	7.8	6.5	5.5	4.7	4.1	3.4	3.0
80	9.0	7.3	6.0	5.0	4.2	3.8	3.3	2.9	2.4	2.0
85	6.0	4.8	3.9	3.3	2.8	2.5	2.2	2.0	1.7	1.4
90	4.0	3.2	2.7	2.2	1.9	1.7	1.5	1.4	1.2	1.1

## • Impedance – Relative humidity curve

