Crank mechanism

Adam

VIEW IN BROWSER

updated 21. 11. 2023 | published 21. 11. 2023

Summary

A simple crank mechanism

Learning > Engineering

Tags: mechanism slider crank

Update 21.11.2023: added new part slider with clearance fit and the crank with bigger hole for screw

A simple crank mechanism



Other necessary components:

- 1x screw M3-10

I recommend to print parts crank.stl and slider.stl wiht 60% of printing speed.

Printing parameter:

- Nozzle: 0,4 mm
- Layer height: 0,2 mm
- Perimeters: 2
- Infill: 15%
- Supports: None
- Filament: PLA

Model files

rod.stl



base.stl

crank.stl

I recommend to print with 60% printing speed

crank_clearence_fit.stl

The crank with bigger hole for M3 screw. Use it if hole in the crank.stl is to tight for screw.

slider.stl

I recommend to print with 60% printing speed

slider_clearence_fit.stl

The slider with more clearance fit. Use it if the slider.stl is to tight.

License

This work is licensed under a
Creative Commons (International License)

Public Domain

✔ | Sharing without ATTRIBUTION
✔ | Remix Culture allowed
✔ | Commercial Use
✔ | Free Cultural Works
✔ | Meets Open Definition