
AISIN
We Touch the Future

Satu AISIN
COLLABORATION, INNOVATION



SHARING & FOLLOW UP DIGITALISASI HENKATEN

/ © AISIN INDONESIA, AUTOMOTIVE All Rights Reserved.

SUDUT PANDANG KLAUSAL 3 PILLAR

BRONZE

Kontrol henkaten	**8) Dilakukan kontrol henkaten**	
	①Rule kontrol (4M) jelas dan dipahami	①-1 Ada rule kontrol
		①-2 Dicatat pada control sheets
	②Problem karena henkaten dipahami betul	② Penanggulangan terhadap problem masa lampau karena henkaten dan point-nya jelas


SILVER

Kontrol henkaten	**8) Kontrol henkaten nya dilakukan**	**8) Kontrol henkaten nya dilakukan**	①-1 Kontrol henkaten nya dilakukan sesuai rule
	①Rule kontrol (4M)nya jelas, dan dipahami	① Dilaksanakan dengan 4M sesuai rule kontrol (ada history nya)	①-2 Ada history kontrol henkaten
	②Problem karena henkaten nya dipahami	② Melaksanakan aktivitas pengurangan risiko henkaten (advance education & training, dll.)	② Countermeasure nya dijalankan dengan urutan dari yang risikonya tinggi dulu

/ © AISIN INDONESIA, AUTOMOTIVE All Rights Reserved.

SUDUT PANDANG KLAUSAL 3 PILLAR

Kontrol henkaten	**8) Dilakukan kontrol henkaten**	
	①Rule kontrol (4M) jelas dan dipahami	①-1 Ada rule kontrol
		①-2 Dicatat pada control sheets
	②Problem karena henkaten dipahami betul	② Penanggulangan terhadap problem masa lampau karena henkaten dan point-nya jelas




Kekurangan Point 1

1. Rule Menjalankan Henkaten
2. Rule Arti Henkaten Simbol

/ © AISIN INDONESIA, AUTOMOTIVE All Rights Reserved.

SUDUT PANDANG KLAUSAL 3 PILLAR

Kontrol henkaten	**8) Dilakukan kontrol henkaten** ①Rule kontrol (4M) jelas dan dipahami	①-1 Ada rule kontrol
		①-2 Dicatat pada control sheets
	②Problem karena henkaten dipahami betul	② Penanggulangan terhadap problem masa lampau karena henkaten dan point-nya jelas



Henkaten History

Thursday, 13 March 2025

Show 10 entries

Search:

Date	Type	Line	Time	Abnormality	Henkaten Document	Category	Table Henkaten No.	Troubleshoot	Troubleshoot Document	Troubleshoot Time	status	Safety	Quality Inspection				Done by	Approval		
												Result Check	Report Abnormality	Part	Before	After		Leader	Supervisor	Manager
2025-03-12	MACHINE	AS003	22:32:13	Bitscrewpatah Autotightening Pos.6 no.3 (1712)	No Document	Productivity Issue	11	Ganti Bitscrew by JP, Cek B/A by QUC	No Document	2025-03-12 22:32:58	solved	ok	no need	D41A	ng	ok	Muhamad Lutfi Hakim	✓	Waiting SPV	Waiting SPV
2025-03-12	MACHINE	AS003	10:35:20	Mesin leak alarm cycle time over	No Document	Productivity Issue	9	PE setting sensor rotation torque	No Document	2025-03-12 10:51:36	solved	ok	no need	D41E	ng	ok	Arif Supriyanto	✓	Waiting SPV	Waiting SPV
2025-03-11	MACHINE	AS003	11:53:30	Bit screw lifetime pos 4	No Document	Productivity Issue	11	Ganti Bit screw By JP Check B/A By QC	No Document	2025-03-11 14:55:20	solved	ok	no need	D72F	ng	ok	Arif Supriyanto	✓	Waiting SPV	Waiting SPV
2025-03-08	MACHINE	AS003	09:48:32	Bit screw patah pos 4 as004	No Document	Productivity Issue	11	Jp Ganti Bit screw patah, QC Check Part Before after	No Document	2025-03-08 09:49:56	solved	ok	no need	D72F	ng	ok	Arif Supriyanto	✓	Waiting SPV	Waiting SPV
2025-03-06	MACHINE	AS003	17:10:40	bit screw mesin autotightening patah	No Document	Productivity Issue	11	jp ganti bit screw patah, qc check part before & after	No Document	2025-03-06 17:12:02	solved	ok	no need	D41E	ng	ok	Arif Supriyanto	✓	Waiting SPV	Waiting SPV
2025-03-06	MACHINE	AS003	11:05:24	Bitscrewpatah Pos.4 no.1 (2442/3000)	No Document	Productivity Issue	11	Ganti Bitscrew by JP, Cek Part B/A by QuC	No Document	2025-03-06 14:10:35	solved	ok	no need	D41T	ng	ok	Muhamad Lutfi Hakim	✓	Waiting SPV	Waiting SPV
2025-03-05	MACHINE	AS003	10:57:33	BitscrewLT Pos.4 (3017/3000)	No Document	Productivity Issue	11	Ganti Bitscrew & Cek Part B/A by JP	No Document	2025-03-05 10:58:38	solved	ok	no need	D41A	ok	ok	Muhamad Lutfi Hakim	✓	Waiting SPV	Waiting SPV
2025-03-04	MACHINE	AS003	21:08:56	Bit screw patah mesin autotightening	No Document	Productivity Issue	11	Jp ganti bit screw patah, Qc Cek Part before & after	No Document	2025-03-04 21:09:58	solved	ok	no need	D41E	ng	ok	Arif Supriyanto	✓	Waiting SPV	Waiting SPV
2025-02-28	MACHINE	AS004	03:09:23	Bit screw patah pos 4 counter 905/1000	No Document	Productivity Issue	11	Jp ganti bit screw , qc cek torque screw before after	No Document	2025-02-28 03:10:42	solved	ok	no need	Tcc d72f	ng	ok	Midan Nopiandi	✓	Waiting SPV	Waiting SPV
2025-02-27	MACHINE	AS004	05:13:07	Bit screw patah pos 4 counter 929/1000	No Document	Productivity Issue	11	Jp ganti bit screw , Qc cek torque screw before after	No Document	2025-02-27 05:14:01	solved	ok	no need	Tcc 4A91	ng	ok	Midan Nopiandi	✓	Waiting SPV	Waiting SPV


Showing 1 to 10 of 770 entries

Previous 1 2 3 4 5 ... 77 Next

/ © AISIN INDONESIA, AUTOMOTIVE All Rights Reserved.

SUDUT PANDANG KLAUSAL 3 PILLAR

Kontrol henkaten	**8) Dilakukan kontrol henkaten** ①Rule kontrol (4M) jelas dan dipahami	①-1 Ada rule kontrol
		①-2 Dicatat pada control sheets
	②Problem karena henkaten dipahami betul	② Penanggulangan terhadap problem masa lampau karena henkaten dan point-nya jelas



Tambahan Point

1. Bukti Edukasi Training ke Member

/ © AISIN INDONESIA, AUTOMOTIVE All Rights Reserved.

SUDUT PANDANG KLAUSAL 3 PILLAR

Kontrol henkaten	**8) Kontrol henkaten nya dilakukan**	**8) Kontrol henkaten nya dilakukan**	①-1 Kontrol henkaten nya dilakukan sesuai rule
	①Rule kontrol (4M)nya jelas, dan dipahami	① Dilaksanakan dengan 4M sesuai rule kontrol (ada history nya)	①-2 Ada history kontrol henkaten
	②Problem karena henkaten nya dipahami	② Melaksanakan aktivitas pengurangan risiko henkaten (advance education & training, dll.)	② Countermeasure nya dijalankan dengan urutan dari yang risikonya tinggi dulu

HENKATEN

Show 10 entries Search:

Date	Abnormality	Henkaten Document	Category	Table Henkaten No.	Troublesho
2024-10-09	atah pos 4 , counter)	No Document	Safety Issue	11	JP ganti bit screw ,QC ce before dan after
2024-10-03	nk Kompresor (mesin valve test) mengisi terus/berisik	No Document	Safety Issue	10	FU MTE, MTE ganti Boost proses 3 pcs & Cek mast OK)

/ © AISIN INDONESIA, AUTOMOTIVE All Rights Reserved.

SUDUT PANDANG KLAUSAL 3 PILLAR

KESIMPULAN DARI SUDUT 3 PILLAR

1. Penambahan menu upload untuk standard henkaten
2. Penambahan menu upload Skill Matriks
3. Tampilan awal di dashboard mungkin ditambahkan ini dibawah linenya itu keterangan Jp + Jumlah Mp di line tersebut
4. Perubahan status/judgement Ketika ada henkaten. Jika X → △

/ © AISIN INDONESIA, AUTOMOTIVE All Rights Reserved.

Satu AISIN

COLLABORATION, INNOVATION

