ACCRETECH

TOSEI (THAILAND) CO.,LTD.

AMATA CITY CHONBURI INDUSTRIAL ESTATE
700/633 Moo 7, Tambon Don Hua Roh
Amphur Muang Chonburi 20000
TEL: (66)38-193-282 FAX: (66)38-193-284
TAX ID. NO. 0115547000743

Issue	Checked	Approved
5 Feb 24 Uthen TSET	5 Feb 24 Kittipong TSET	5 Feb 24 Somsak Manager

Quotation Valid Until : 05-Jun-2024
Type : 15

QUOTATION
(Local Condition)

CUSTOMER NAME	NMB-MINEBEA THAI LTD. (LOCAL)	DATE	5 February 2024
ATTN. NAME	K. NATTHANICHA	QUOTATION NO.	6015062
ADDRESS	1 MOO 7, PHAHOLYOTHIN ROAD., K.M. 51 TAMBON CHIANG RAK NOI, AMPHOE BANGPA-IN AYUTTAYA PROVINCE THAILAND 13180	DATE OF DELIVERY	14 days after received P/O
FAX. NO.		TERM OF PAYMENT	30 Days From Invoice
PLACE OF DELIVERY	PMA		

ITEM	DESCRIPTIONS PRODUCT NO	NAME	SPEC	Q'ty	UNIT PRICE (BAHT)	AMOUNT (BAHT)
		Inspection & Repair		1(SET)		37,000.00
		Model : Sigma E-TS-1151B-P6, S/N : 507280				
		INCLUDED				
1	5RS-127	Repair fee Sigma		1		
2	0065702	LVDT ASSY		1		
3	5RS-006	SUPPLIES ASSY SET SIGMA		1		
4	0065732	CABLE ASSY 6M		1		
5	5RS-140	Expedited check Sigma		1		
6	5RS-153	Expedited repair Sigma		1		
	Remark:	1) This quotation is for NMB-MINEBEA THAI LTD. (LOCAL)				
		2) Exchange Rate : 100 JPY = 24.5900 THB (Information from NMB for 02/2024)				
		3) Sale Contact :K.Noothchanat Mobile:081-869-8290				
		Email :Noothchanat@tosei.co.th				
		4) We will return repair unit if over 5 months after register for items which customer no need to repair.				

บริษัท โทเซอิ (ประเทศไทย) จำกัด ACCRETECH TSE TOSEI (THAILAND) CO.,LTD.

Please send your purchase order by email and send to mail : **po.tset@tosei.co.th**
Please remark quotation number or attach quotation sheet in PO order all time for protect mistake order.

Thirty Nine Thousand Five Hundred Ninety Baht Only	TOTAL	37,000.00
	ADDED TAX 7%	2,590.00
	GRAND TOTAL	39,590.00

Customer Confirm Ordering

		Name :
		Position :
		Tel :
		Date :
Stamp	Signature	

Important notice

The product (s) as quoted above may be imposed an embargo on the exportation from Japan even before or after signing a contract when the MET

(Ministry of Economy, Trade and Industry) judges that the goods come under Security, Export Control Law of Japanese Government. You are requested to notify to

TOSEI (THAILAND) CO., LTD. In advance by written before you transfer or resell the product(s) to other parties.

TOSEI (THAILAND) CO.,LTD.
AMATA CITY CHONBURI INDUSTRIAL ESTATE
700/633 Moo 7, Tambon Don Hua Roh, Amphur Muang Chonburi 20000
TEL: (66)38-193-282-3 FAX: (66)38-193-284

REPAIRING REPORT SHEET

Model Name :	**E-TS-1151B**	Serial No. : **507280**	Request Date : **2/2/2567**	Report Date : **4/2/2567**
Customer Name :	**NMB-MINEBEA THAI LIMITED (LOCAL)**	Customer Incharge : **K.Natthanicha**	Checked Date : **4/2/2567**	Quotation No. : **6015062**
Agency Name :	**TOSEI (THAILAND) CO., LTD.**	Tosei Incharge : **K. Nootchanat**	Repaired Date :	

Item	Check item	Judgment		NG Parts	
1	**Overview**			Pic.1	Pic.2
	1 Body	OK			
	2 Cable Assy	OK			
	3 Air Retact	-			
2	**Measuring**	**G1**	**G2**		
	1 Signal	OK	NG		
	2 Measuring Force (N.)	0.3	Can't check		
	3 Front Travel (mm.)	-0.25	0.56		
	4 Repeatability (mm.)	7.5	Can't check	Pic.3	Pic.4
	5 Linearity (mm.)	4.2	Can't check		
	6 Retract (mm.)	-	-		
3	**Inside**				
	1 Insulation Cable Ass'y (MΩ)	NG			
	2 Insulation Bobbin Ass'y (MΩ)	NG			
	3 Lever	OK			
	4 Core assy	OK			
	5 Board	OK			

4 Investigation and Repairing Comment

1 First investigation result

- We found that the insulation gauge is below normal.
- We found that the measuring force is below normal.
- We found that the front travel more than normal.
- We found that the repeatability more than normal.
- We found that the linearity more than normal.

Repair Judgement

NG

2 Checking inside gage

- We found that the insulation cable assy is below normal.
- We found that the insulation bobbin assy is below normal.
- We found that the leaf spring is bend.
- We found that the silicon oil have coolant and dirty.

3 After repair status.

Repair Incharge

Uthen