
PART No.
TGM-19-170R-xx

2 REV.

Rework Hole for Pin Taper

Item	L	Check
-01	~~12~~	~~Preecha~~
2 -02	10.1	Preecha
-03		
-04		
-05		



MinebeaMitsumi Inc.
Copy issued Uncontrolled
7/8/2569
Engineering Design center
G/M.1 & M/A. Div.

Note:
1. Symbol x.xx for must control spec.
2. Symbol (x.xx) for not control spec.
3. Break all Corner approx by C0.1
4. General Tolerance ±0.1
5. Item-20 for ØD = Ø50 please control spec. = 0.2 mm.

REV.	ECN No.	DATE	NAME	DESCRIPTION
1	----	----	---	ENGINEERING RELEASE
2	----	7 Aug'26	Preecha	Add: Item -02

UNLESS SPECIFIED C0.1 OR R0.1	
GENERAL TOLERANCE	
JISB0405 MACHING WORKING	
LESS THAN 0.5	±0.05
0.5 ~ 6	±0.1
6 ~ 30	±0.2
30 ~ 120	±0.3
120 ~ 400	±0.4
400 ~ 1000	±0.8
ANGLE	±1°

0.8S 6.3S 25S 100S UNCUT

M/C. Mercury | Q'ty 1
MATERIAL (SCM21)
FINISH (Liquid Honing)
HEAT TREATMENT (HV 750~)

List Request No. 229/26
3 RD ANGLE
SCALE : | SHEET / | UNIT (mm.)

DETAILED	DESIGNED	CHECKED	APPROVED
Phalachai	Aphisek	Preecha	Preecha

DATE 6 Aug' 26

NMB MinebeaMitsumi Inc.
General Machining Parts Div. 1

TITLE: Rework ball screw

PART No. TGM-19-170R-xx

2 REV.