
PART No.
TGM-52-046E-xx


2 REV.


Note:
1. All Point fix by Welding, Spot
2. Break all Corner NO Sharp Edge
3. Basket (Punching Tray) Can to overlap
4. NO Contam Rusty
5. NO twisted (frame)
6. After production, it must be cleaned.

Item	∅D	L	W	Check
-01	3.0x5.0P33%	300	230	Preecha
-02	2.0x3.0P40%	300	230	Preecha
-03	5.0x8.0p35%	300	230	Preecha tatree





DETAIL B
SCALE 2 : 1






DETAIL H
SCALE 2 : 3







DETAIL X
SCALE 2 : 3.5



SECTION A-A
SCALE 1 : 2





REV.	ECN No.	DATE	NAME	DESCRIPTION
1	----	----	---	ENGINEERING RELEASE
2	----	18 Feb' 12	Preecha	Add: 29.5 etc.;

MinebeaMitsumi Inc.
Copy issued Uncontrolled
30/6/2568
Engineering
Design center
G/M.1 & M/A. Div.

400 ~ 1000 ±0.8
ANGLE ±1°

0.8S 6.3S 25S 100S ~ UNCUT

M/C. -
Q'ty 1
MATERIAL SUS 304
FINISH brushed surface
HEAT TREATMENT -

List Request No. 2023
3RD ANGLE
SCALE : SHEET / UNIT (mm.)

DETAILED	DESIGNED	CHECKED	APPROVED
Phalachai	Aphisek	Preecha	Preecha

DATE 7 Nov' 02

NMB MinebeaMitsumi Inc.
General Machining Parts Div. 1

TITLE: Basket (Punching Tray)

PART No. TGM-52-046E-xx

2 REV.