Code: 13MBA1010

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT, TEKKALI (AUTONOMOUS)

I MBA II Semester Regular/Supplementary Examinations, April - 2016 PRODUCTION AND OPERATIONS MANAGEMENT

Time: 3 hours Max Marks: 60

Answer any Five questions All questions carry EQUAL marks Question No.8 is Compulsory

- 1. a) Distinguish between manufacturing and service?
 - b) What are the various types of production systems? Explain
- 2. Write a detailed note on Flexible Manufacturing Systems(FMS) and sketch different layouts used in FMS.
- 3. How Material Requirement Planning (MRP) is different from Inventory control. Also explain the different inputs of MRP.
- 4. A raw material undergoes two machining process at machines turning (M1) and grinding (M2) in sequence before becoming a finished item before. There are six raw material available in buffer for machining and the time required performing the turning & grinding are given below.

Book	1	2	3	4	5	6
M1	Δ	8	2	6	5	7
M1 M2	7	3	5	2	1	5

Calculate the total elapsed time to complete the job and also the idle times at both the machines.

- 5. What is Productivity? Explain the various elements in the Total Productivity Model..
- 6. Compare Method Study and Work Measurement. Also explain how they influence the overall improvement of an Organization.
- 7. Describe the following
 - a) Control Chart for Attributes
 - b) Six Sigma

Code: 13MBA1010

8.CASE STUDY.

15 samples of size 4 were drawn and the following Measurement were made.

Sample No.	Observations		
1	40, 28, 41, 14		
2	50, 44, 60, 58		
3	33, 23, 60, 71		
4	30, 41, 42, 31		
5	37, 38, 35, 39		
6	38, 42, 34, 24		
7	42, 39, 36, 42		
8	19, 29, 28, 24		
9	19, 30, 36,39		
10	44, 38, 43, 34		
11	42, 24, 45, 34		
12	35, 44, 59, 61		
13	24, 43, 40, 45,		
14	33, 44, 45, 32		
15	18, 36, 22, 21		

Determine UCL and LCL for X-chart and R-Chart and draw these charts (for n=4, A2=0.729, D3=0 & D4=2.282)