



# **CASIO CZ 101 / 1000 SERVICE MANUAL DIAGRAMS**

Document Size 420x297mm (A3) - Print at 65% Horizontal on A4 Printer



## 1. SCHEMATIC DIAGRAM


1 - 1. PCBs M4152-MA1M, CN3M






1 - 3. PCBs M4152 - MA2M , CN5M






1-2. P.C.B. M4150-CN2M



1-3. P.C.B. M4150-CN4M



1-4. P.C.B. M4150-KY2M

