## DETROIT DIESEL



No.: 06 TS - 03 January 24, 2006

TO: DDC Distributors, FLLC Dealers

FROM: Technical Service

SUBJECT: New Oil Pan For MBE4000 Engines

## **ISSUE**

New 36L capacity front sump oil pan for certain MBE4000 engines.

## ADDITIONAL INFORMATION

MBE has installed a new front sump oil pan (P/N: 4600100713) that contains 36L (38 qt.) of oil instead of the former 40L (42.3 qt.) oil pan (P/N: 4760101013) effective with engine serial number 0460833530.

- Do not overfill the crankcase when filling the engine with oil. Refer to the MBE4000
  Operators Guide (6SE411) for information on correctly filling the engine with oil and checking the level on the dipstick.
- The new oil pan is used on the following engines:
  - All EGR engines with front sump
  - Non-EGR engines with front sump for Right Hand Drive export applications (Australia, New Zealand, etc.)
- The new oil pan is NOT used on the following engines:
  - Non-EGR engines with front sump for Left Hand Drive applications (Mexico, etc.)
  - Any rear sump application
  - These engines will convert to the new 36L pan in late 2006
- Other new parts associated with this change are:
  - Oil pickup tube
  - Dipstick and dipstick tube
  - Oil fill tube
  - Bracket for dipstick tube and oil fill tube
  - Oil centrifuge cover
- Do NOT install the new 36L oil pan on an engine that was built with a 40L oil pan without fully investigating all of the changes between the two particular engines
- Engines with the new oil pan are identified with a "36L" sticker on the engine oil fill cap (See Figure 1 below)





Figure 1 – Identifying Label on Engine Oil Fill Cap

## **CONTACT INFORMATION**

Please contact the DDC Customer Support Center at 313-592-5800 if you have any questions.