How to do Freightliner DETROIT Returns

CMCS

6/14/06

CMCS login <u>Web Link to Detroit Diesel Core Returns</u>
Login = Idrrd001
Password = dirtyboy

[Make note - if change password advise Chuck, Michael and Aaron]

See following for Power Point Training Power Point Training Presentation

Step 1 - Determine what cores we can return (Eligibility)
Create NEW Core Owed Report (CRO50)
These 2 boxes need to be checked
X Reman Center = E (for East)
X On Highway

After file generates - Go to Reports - View and Print.

Step 2 - After printing CORE OWED REPORT Check off all cores we have ready to be returned - that are on CORE OWED REPORT

Need to do a test return.....