

**No.: 05 TS - 04** May 4, 2005

TO: DDC Distributors and FLLC Dealers

FROM: Technical Service

ATTN: General Manager, Service Manager

SUBJECT: New Fuel Pump & Regulator for Series 60 EGR DDEC V Engines

#### **ISSUE**

Detroit Diesel Corporation has introduced a new fuel pump and combination pressure regulator/check valve for use on Series 60 EGR engines equipped with DDEC V. These changes will improve the reliability of the N3 fuel injectors used on these engines.

### **REQUIRED ACTION**

The changes are effective with engine unit serial number 06R0814266 built on December 21, 2004. For fuel pump repairs on earlier DDEC V engines, the new fuel pump and combination pressure regulator/check valve <u>MUST</u> be installed together.

## Details of Change

• New fuel pump (P/N: 23535207) replaces former fuel pump (P/N: 23532874). Visually, the two pumps differ only by the part number. See Figure 1 below.




Figure 1 - New Fuel Pump (P/N: 23535207)



- New combination pressure regulator/check valve (P/N: 23535129) replaces former check valve (P/N: 23516993).
- New plain 90 degree elbow (P/N: 23535130) replaces former R80 90 degree elbow (P/N: 8929725).
- Former nipple pipe (P/N: 23530009) is no longer used.

# See Figures 2 and 3 below




Figure 2 - Former Check Valve, R80 Elbow, & Nipple




Figure 3 - New Combination Pressure Regulator/Check Valve & Plain Elbow

#### **REPAIR PROCEDURES**

The new fuel pump and combination pressure regulator/check valve <u>MUST NOT</u> be mixed with the old components.

Installing a new combination pressure regulator/check valve with the former fuel pump can cause:

- High fuel inlet restriction
- Reduced fuel filter life
- Performance issues

Installing a new fuel pump with the former R80 elbow and check valve can cause the failure of N3 injectors.

For the small number of engines with a DDC-installed primary fuel filter, the fuel tube connecting the primary filter to the fuel pump <u>MUST</u> be replaced with a larger diameter tube.

- On single cylinder air compressor applications, new tube (P/N: 23535197) replaces former tube (P/N: 23530108).
- On twin cylinder air compressor applications, new tube (P/N: 23535198) replaces former tube (P/N: 23531052).
- New fuel tube support clip (P/N: 02236474) replaces former support clip (P/N: 23534169).
- New primary fuel filter outlet fitting (P/N: 23530394) replaces former fitting (P/N: 5244760424).

# See Figure 4




Figure 4 - New Fuel Tube for Engines with DDC- Installed Primary Fuel Filter

Fuel pressure measured at the fuel pump outlet has changed dramatically. See table 1 below for some <u>BASIC</u> guidelines on the former and new pressures. These are nominal values and will be subject to variation based on vehicle differences such as fuel tank level and fuel filter configuration.

| RPM  | Former Fuel Pump Outlet Pressure (psig) | New Fuel Pump<br>Outlet Pressure<br>(psig) | Former Fuel Spill Flow (gpm) | New Fuel Spill<br>Flow (gpm) |
|------|---|--|------------------------------|------------------------------|
| 2200 | 79                                      | 28   | 1.1                          | 1.7                          |
| 2100 | 79                                      | 27   | 1.1                          | 1.6                          |
| 1800 | 78                                      | 24   | 1.1                          | 1.4                          |
| 1500 | 76                                      | 22   | 1.1                          | 1.2                          |
| 1200 | 65                                      | 21   | 1.0                          | 1.0                          |
| 900  | 40                                      | 19   | 0.8                          | 0.7                          |
| 600  | 20                                      | 18   | 0.6                          | NA                           |

Table 1 – Guidelines for Former and New Fuel Pump Outlet Pressures/Fuel Spill Flows

### **CONTACT INFORMATION**

Please contact the Detroit Diesel Customer Support Center at 313-592-5800 if you have any questions.