
Eaton® Fuller® Clutch Core Return Identification


The number of visible cover assembly springs indicates which cores Eaton will accept.

- 9-Spring Easy-Pedal™ Style Cores Eaton Accepts
- 6-Spring Angle Spring Style Cores Eaton WILL NOT Accept*

Accepted Style

Easy-Pedal clutches have 9-springs visible on the back of the cover assembly.





Not Accepted Style*

Angle spring clutches have 6-springs visible on the back of the cover assembly.

Eaton Corporation Clutch Division 201 Brandon Street Auburn, IN 46706

- * Eaton will only accept 6-spring Angle Spring cores that meet the following 2 requirements:
 - Must be a reman purchased before April 1, 2001.
 - Must meet core return eligibility.

