Assignment 7: Logging and Interpreting AT Command Errors

Ajai Paul Kenny

July 20, 2025

1. Objective

The goal of this assignment is to explore and document the different types of errors encountered when using AT commands on GSM/LTE modules or emulators. Each error scenario is tested using practical examples, logged, and manually interpreted for educational and troubleshooting purposes.

2. Setup Used

• Emulator: CelerSMS AT Emulator (limited to basic commands)

• Terminal: PuTTY, 9600 baud, COM4

• Operating System: Windows 10

• (Optional) Real modem:Cavli or SIM7600

3. Error Case Studies

3.1. 1. Syntax Error

Command Used:

AT+XYZ

Response:

ERROR

Explanation: The command **+XYZ** does not exist in the AT command set. This is a typical **syntax error** triggered when an invalid, misspelled, or unsupported command is used.

Resolution: Check the AT command manual of the modem being used. Use AT+CLAC (if supported) to list available commands.

3.2. 2. Missing Parameter Error

Command Used:

AT+CSQ=

Response:

ERROR

Explanation: The AT+CSQ command does not require parameters. Adding an equals sign incorrectly implies parameter usage. Many commands only support the read (' $\dot{\xi}$) or test ('= $\dot{\xi}$) format.

Correct Usage:

AT+CSQ

Resolution: Refer to the correct command syntax in the modem documentation. Avoid using '=' unless required.

3.3. 3. Invalid Parameter Error

Command Used:

AT+CMGF=5

Response:

ERROR.

Explanation: AT+CMGF sets the SMS message format. Valid values are:

- $0 = PDU \mod e$
- 1 = Text mode

Using 5 is invalid and rejected by the modem.

Resolution: Use either AT+CMGF=0 or AT+CMGF=1. Use AT+CMGF=? to check supported values.

3.4. 4. Network/Socket Connection Error

Command Used (on real modem):

```
AT+QIOPEN=1,0,"TCP","1.1.1.1",65535,0
```

Response:

+QIOPEN: 0,565

Explanation: The modem attempted to open a socket but failed. The error code 565 indicates:

"Connection timeout or failure — unreachable server or port"

Resolution:

- Ensure SIM is registered on network (AT+CREG?)
- Check PDP context and APN (AT+CGDCONT?)
- Verify server IP/port availability

3.5. 5. SIM Not Ready / Registration Error

Command Used:

AT+CPIN?

Possible Response:

+CPIN: SIM PIN

OK

Explanation: The SIM card is inserted but not yet unlocked with its PIN code. As a result, any network-related command like AT+CREG? or AT+CGACT will fail.

Resolution:

• Enter the PIN using: AT+CPIN="1234"

• Wait for SIM to register and respond with +CPIN: READY

4. Conclusion

Understanding and interpreting AT command errors is a key skill in embedded systems and IoT communication. Through this assignment, we've covered a range of common error types, the reasons behind them, and steps for resolving each. This improves both development efficiency and field-level troubleshooting capabilities.

Appendix: Additional Useful Commands

- AT+CLAC List all supported AT commands
- AT+CREG? Check network registration status
- AT+CGDCONT? View current PDP context (APN settings)
- AT+CPIN? Check SIM card state