Module 1: The evolution of the q parameter

Course 2 of Optical Engineering: Optical efficiency and resolution

with Dr. Robert R. McLeod and Dr. Amy C. Sullivan

How does q evolve with transfer & refraction?

Transfer

$$q_1 = z_1 + j z_0$$
 $q_2 = z_2 + j z_0 = q_1 + (z_2 - z_1)$

$$q_2 = q_1 + \Delta z$$

Refraction

$$\frac{1}{q(z)} = \frac{1}{R(z)} - j \frac{\lambda}{\pi w^2(z)}$$

$$\frac{1}{R'} = \frac{1}{R} - \frac{1}{f}$$

$$\frac{1}{q'} = \frac{1}{q} - \frac{1}{f}$$

$$q' = \frac{q}{-q/f + 1}$$

Thin lens equation expressed as change in curvature.

NOTE GAUSSIAN BEAM SIGN CONVENTION!

Change of q at thin lens

Solve for q'

First order design w/ Gaussian beams (1/2)

Evolution equation:

$$q' = \frac{Aq + B}{Cq + D}$$

Transfer

$$\mathbf{7}_{k} = \begin{bmatrix} 1 & t_{k}' \\ 0 & 1 \end{bmatrix}$$

$$q' = \frac{1q + t'_k}{0q + 1} = q + t'_k \checkmark$$

Refraction

$$\boldsymbol{\mathcal{R}}_k = \begin{bmatrix} 1 & 0 \\ -\phi_k & 1 \end{bmatrix}$$

$$q' = \frac{1q+0}{-\phi_k q+1} = \frac{q}{-q/f+1} \quad \checkmark$$