## Verifying process gauges, analog and digital



Both analog and digital process gauges need to be verified to detect errors related to drift. environment, electrical supply, addition of components to the output loop, and other process changes. Pressure gauges may be verified in the field or at the bench. Field calibration may save time, and allows for troubleshooting in the process environment. Multifunction calibrators make it easier to do this with one tool, and documenting calibrators make it easier to follow procedures, capture data and document results. Bench calibration provides an environment where the gauge can be cleaned, inspected, tested, and recertified under reference conditions for the best possible accuracy.

## Suggested test tools







2700G Series Reference Pressure Gauges See pg 13



Fluke 3130 Portable Pressure Calibrator See pg 14