

SEE IT. SAVE IT. SHARE IT.

All the facts, right in the field.



Fluke Connect™ is the best way to stay in contact with your team without leaving the field. See the tools that save you time and increase your productivity.

- Connect your tools. Connect your data.
- · Share from anywhere.
- All your measurements. All in one place.
- Save time reporting.
- · Troubleshoot faster.
- Lock down your data.



Download the Fluke Connect[™] app at







Fluke Ti90 Thermal Imager Fluke Ti95 Thermal Imager Fluke v3000 FC Wireless AC Voltage

Module

Fluke 3000 FC Wireless Digital Multimeter Fluke a3000 FC Wireless AC Current Clamp Module Fluke t3000 FC Wireless K-Type Temperature

Module

Fluke a3001 FC Wireless iFlex AC Current Module Fluke a3002 FC Wireless AC/DC Current Module

The NEW Fluke Fluorescent Light Tester

Save time, reduce costs, easy to use; performs all essential lighting tests in less then 30 seconds.

- Lamp Test: without removing from fixture
 - · Ballast Test: easily determine if ballast is working
 - Ballast-type text: identify magnetic and electronic ballasts
 - Non-contact voltage: quick check for voltage presence
 - Pin continuity test: if filaments have continuity



Fluke 1000FLT Fluorescent Light Tester

Fluke 6200-2 and 6500-2 Portable Appliance Testers

Perform more tests each day! The low weight, small size, one-touch solutions.

Improved auto-test capabilities to help you increase the number of tests completed each day.

- · 'One-touch' testing
- Save time: pre-set pass/fail levels
- Easy reading: large backlit display
- Rapid data entry
- Back-up data storage and transfer: additional USB memory drive
- Pre-set, auto-test sequences

NEW

- Colour Dot Matrix Display
- 250V Insulation Test
- 110V Test Functionality
- RCD Test



Optional accessories:

- DMS 0702/PAT software
- SP-SCAN-6000 barcode scanner
- SP6000 printer

Also available as a kit.



Fluke Ti90 and Ti95 Thermal Cameras

The only wireless enabled industrial thermal imager at this price point.



Save more time than before and find potential problems before they become costly failures with these new thermal imagers from Fluke.



- Get up to 84% better spatial resolution for superior image
- View images on 16% larger screen the largest LCD in its class
- Communicate back to your supervisors with your smart phone without having to leave the site with the Fluke Connect™ app
- Built Fluke tough... durable enough to handle a 2-meter drop, and IP54-rated
- FREE SmartView[®] Imaging Analysis and Reporting Software

Temperature solutions

Distance to spot

Temperature range



· Hot/cold markers

· Analysis software

Image storage

Fluke VT04, Fluke VT04A

Fluke 62MAX, Fluke 62MAX+

PERMANENTLY

- · Min/max/avg/dif
- Dust/water resistant (IP54)
- Fluke 561
- Combined · Data logging · Combined IR + contact
- IR+contact HVAC
- applications
- **Fluke 566, Fluke 568**
- Fluke 572-2
- Data logging
- Hi/Lo alarm
- Min/max/avg/dif
- IR+contact

	Heat	map	Exact spot positioning					
Features	VTO4* VTO4A		62MAX	62MAX+	561	566	568	572-2
	Visual IR thermometer		Infrared thermometer		Multipurpose thermometer			High termperature
Temperature	-10 to 250 °C		-30 to 500 °C	-30 to 650°C	-40 to 550 °C	-40 to 650 °C	-40 to 800 °C	-30 to 900 °C
D:S**	9:1	9:1	10:1	12:1	12:1	30:1	50:1	60:1
Laser sighting	No laser necessary		Single	Dual	Single-point	Single-point	Single-point	Offset dual

Special promotions NEW Fluke Multifunction Installation Tester Kits

Fast, lightweight, easy to use, robust and reliable installation tester. Now all models with great offers!







* Offer valid till 30 April 2015 or while supplies last.	Fluke 1652C	Fluke 1653B	Fluke 1654B
Fast high current loop test	•	•	•
Reliable 3-wire loop test	•	•	•
No complex multi-level menus: rotary dial clearly indicates selected function	•	•	•
Easy test lead compensation: Zero adapter	•	•	•
Extended memory	-	-	•
mΩ resolution: loop & line resistance	-	-	•
Variable RCD current mode for customised settings	•	•	•
Test smooth DC sensitive RCDs	-	-	•
PASS/FAIL indication for RCD tests	•	•	•





FLUKE TESTGUIDE

The **NEW** TestGuide app shows electricians in short and clear steps what the actions are for the most common measurements, what to look at and how to interpret the results.

You will also find background articles and in-depth application notes which can be downloaded or send to your email.

Learn more at fluke.co.uk/testguide

Free download at







Fluke Clamp Meters: Readings you can rely on



Wire in tight spaces - panels out of reach - extra large conductors. Noise free measurements for every workspace.



	Fluke 365	Fluke 323	Fluke 324	Fluke 325	Fluke 373	Fluke 374	Fluke 375	Fluke 376
Jaw opening	18 mm	30 mm	30 mm	30 mm	32 mm	34 mm	34 mm	34 mm
Current AC TRMS/DC	200 A AC/DC	400 A AC	400 A AC	400 A AC/DC	600 A AC	600 A AC/DC	600 A AC/DC	1000 A AC/DC
Voltage AC/DC	600 V	600 V	600 V	600 V	600 V	600 V	600 V	1000 V
Continuity	•	•	•	•	•	•	•	•
Resistance	•	•	•	•	•	•	•	•
Capacitance	-	-	•	•	•	•	•	•
Frequency	-	-	-	•	-	-	•	•
Contact temperature	-	-	-10 to 400°C	-10 to 400°C	-	-	-	-
In-rush	-	-	-	-	•	•	•	•
i-Flex	-	-	-	-	-	optional	optional	included (18")

^{*} Free LED Puck Alarm Light offer valid until 30.06.2015, only available direct from Fluke by using special offer voucher, proof of purchase required. Go to www.fluke.ie/promotions to download the voucher and view full terms and conditions or contact Fluke directly.

Fluke Digital Multimeters



Fluke 110 Series True RMS Digital Multimeters

Economic investment in accuracy, simple operation for easy and fast measurements.







Fluke 3000FC Wireless Digital Multimeter

- AC and DC voltage measurements to 1000V
- AC and DC current with 0.01 mA resolution
- Continuity, resistance, diode test, capacitance and frequency measurements
- MIN/MAX Recording
- CAT III 1000 V, CAT IV 600 V; IP54


		Fluke Connect				
	Fluke 113	Fluke 114	Fluke 115	Fluke 116	Fluke 117	Flk 3000FC
True-RMS-readings	AC	AC	AC	AC	AC	AC
DC accuracy	0,5-2,0%	0,5-2,0%	0,5-2,0%	0,5-2,0%	0,5-2,0%	0,09%
Voltage AC/DC	600 V	600 V	600 V	600 V	600 V	1000 V
Min-Max recording / Time stamp + memory	●/-	●/-	●/-	●/-	●/-	●/-
LoZ (low input impedance)	-	•	-	•	•	N/A
Category rating:						
- CAT III/600 V	•	•	•	•	•	-
- CAT III/1000 V, CAT IV/600V	-	-	-	-	-	•
			ACTION!			

Do you know Fluke has a full range of accessories? Below four "must haves" for every technician...









...many more can be found on www.fluke.ie/accessories

Laser Distance Meters

Fluke laser distance meters will become the next essential item on your toolbelt.



Fluke 414D Laser Distance Meter Fluke 419D Laser Distance Meter Fluke 424D
Laser Distance Meter

FLLKE YOLK

Fluke SM100

The fast way to check if your sockets are safe.

- Clear LED indication of wiring status
- Modern, ergonomic design
- Compact and durable
- Simple to use, just plug into a socket for an autotest



Fluke SM100 Socket Master

VoltAlert™

When the tip of the Fluke VoltAlert™ AC voltage detector glows red and the unit beeps, you know there is voltage on the line.

Fluke 2AC VoltAlert™

Electrical Testers



	Fluke T90	Fluke T110	Fluke T130	Fluke T150	Fluke T5-600	Fluke T5-1000
Display	LED's	LED's	LED's/LCD	LED's/LCD	LCD	LCD
Current/Voltage AC/DC	12-690V	12-690V	6-690V	6-690V	100A/1-600V	100A/1-1000V
Other	-	LoZ*	LoZ*	LoZ*/Ohm	Ohm	Ohm

^{*} Low input impedance or switchable load