Selection guide



Hydraulic Pressure Calibrators

This selection guide presents only some of the Fluke Calibration hydraulic pressure calibration line. Other higher accuracy solutions are available for all pressure ranges.

	Manual							Semi Automated																			
	Deadweight Testers							EDWT Electronic Deadweight Tester																			
											6531 6																
	1	2	က	4	5	9	က	4	r.	0	0	0	1	3	4	က	4							_		V	ч
	P3111	P3112	P3113	P3114	P3115	P3116	P3123	P3124	P3125	P3830	P3840	P3860	P3211	P3213	P3214	P3223	P3224	ZM	14M	20M	40M	ZOM	140M	200M	TOM	140M	200M
Fluid type																											
Oil																											
Water																											
Workload																											
Gauges/sensors*																											
Gage																											
Pressure range																											
10 psi (68.9 kPa)																											
15 psi (103.4 kPa)																											
20 psi (137.9 kPa)																											
30 psi (200 kPa)																											
40 psi (275.8 kPa)																											
100 psi (.7 MPa)																											
150 psi (1 MPa)																											
200 psi (1.4 MPa)																											
300 psi (2 MPa)																											
500 psi (3.4 MPa)																											
600 psi (4 MPa)																											
1000 psi (7 MPa)																											
2000 psi (14 MPa)																											
3000 psi (20 MPa)																											
5000 psi (35 MPa)																											
6000 psi (40 MPa)																											
10000 psi (70 MPa)																											
16000 psi (110 Mpa)																											
20000 psi (140 MPa)																											
30000 psi (200 MPa)																											
40000 psi (275.8 MPa)																											
60000 psi (400 MPa)																											

0.015 % reading uncertainty
0.002 % full scale uncertainty
0.0015 % full scale uncertainty
0.0075 psi (0.05 kPa) uncertainty
0.0002 % span uncertainty