

INTRODUCTION

Temperature devices in process manufacturing environments provide measurements to the process plants' control systems. The performance of these temperature instruments is often critical to optimized operation of the process manufacturing plant or proper functioning of the plant's safety systems.

Process temperature instruments are often installed in harsh operating environments, causing their performance and the performance of their sensors to shift or change over time. Keeping these devices measuring temperature within expected limits requires periodic verification, maintenance and adjustments.

APPLICATION SELECTION GUIDE

| | -: 23 | | - 3 | | | | ### SEC. ## | |
|---|-------|-----|---------------|-----------------|---------------|-------|-------------|-------|
| Model number | 75X | 72X | 712B/ 714B | 1551A/ 1552A | 1523/ 1524 | 914X | 7526A | 418X |
| Application | | | | | | | | |
| Calibrate and test RTD sensors | ** | ** | *712B | * | * | Ideal | ** | |
| Calibrate and test thermocouple sensors | ** | | *714B | * | * | Ideal | * | |
| Simulate RTDs | | | 712B | | | | | |
| Simulate thermocouples | | | 714B | | | | • | |
| Generate precision temperatures | | | | | | | | |
| Documenting temperature transmitter calibrations | Ideal | | | | | | | |
| Temperature transmitter calibration with sensor | ** | | | | | | | |
| Calibrating HART smart temperature transmitters | Ideal | | | | | | | |
| Temperature switch/ controller testing and calibration | Ideal | 726 | | | | | | |
| Temperature switch/ controller testing live contacts | Ideal | | | | | | | |
| Infrared thermometer test and calibration | | | | | | | | Ideal |
| Verifying process temperature gauges | | | | | | | | |
| Logging temperature measurements | • | | | 1552A | Ideal | | | |
| Precision temperature measurement | | | | | Ideal | | | |
| Automated batch testing of temperature sensors** | | | | | | Ideal | | |

^{*} Requires a dry-well such as 914X or 910X

^{**} Requires both a dry-well and a 1586A