

Electrical Safety Inspection Report

Product: Extension Board

Overall Status: PASS WITH OBSERVATIONS

Tests:

- Insulation Resistance: PASS
- Earth Continuity: PASS
- Leakage Current: PASS
- High Voltage Test: PASS

Observation:

Power indicator LED brightness inconsistent.

Recommendation:

Verify LED driver resistor tolerance during next production batch.