Set Desire Temperature

Idle motion sensor
(Safe Temp Mode)

System detects motion

Checking Temp

Increase/Decrease temp to comfortable temp

Desired temp
reached

Motion system idle 30 minutes

Reset temp to
Safe Temp Mode

Log temp data

Record log of time
to change data

Increase/Decrease temp to Safe Temp Mode