2/25/2019 harvest.py

```
from busio import I2C
 1
   from board import SDA, SCL
2
 3
   from adafruit_bme680 import Adafruit_BME680_I2C as BME680
4
5
   i2c = I2C(scl=SCL, sda=SDA)
   bme = BME680(i2c, address=0x76)
6
7
8
   temperature = []
9
   gas = []
   humidity = []
10
   pressure = []
11
12
   altitude = []
13
   while True:
14
15
        temperature += [bme.temperature]
        gas += [bme.gas]
16
        humidity += [bme.humidity]
17
        pressure += [bme.pressure]
18
19
        altitude += [bme.altitude]
20
        time.sleep(1)
```