Program 12

write a code to resol Zero flag using push / POP.

Hadress	. Label	OPCode	Donarago	Comments
8002h	* * * * * * * * * * * * * * * * * * *	LXI	SP, FFFFK	Initialize stack
8005h	1. 11.00	PUSH	PS W	location.  Push program Status word (A+1
Service Services		E YE	1.0	into stack
8006 h		POP	Н	grom stack into
are all the	The second second		the second	MU poir.
8007h		Mon	ALL	of L, i.e, Flag data into A.
8 008 h	j.1)	ANI	BFK	portor on AND operation with (BF) to A, for reseting and bit.
800Ah		WOV	L, A	more A's content back into L
800Bh		PUSH	H	Push HL content into Stack
800ch		POP	429	Poip Stack content back into PSW