

## REPAIR ORDER COST PROOF

905 Truck and Trailer

Date: Jul 2, 2024

Unit Owner: 905 Truck and Trailer Repair Invoice To: 905 Truck and Trailer Repair

RO #: WO002543 Page: 1 /1

Location:

Unit U40

VIN 12365497

**Description** Test

Make ALLOY Model DUAL AXLE

Year 2024

License

Tire Size

Engine

Activity Description										
Task	SYS	ASM	Description/Notes	Reason	Actual	Hr Cost	Cost	Sublet		
24	050	000	Accessories Group	1	0.00	0.00	0.00	0.00		
Part No	0.		Description		Actual Part	Unit Cost	Cost	Sublet		
BOLT1			Bolt One		1 EA	25.00	25.00	0.00		
0220			Test		1 EA	50.00	50.00	0.00		
122930	0		EXHAUST PIPE		1 EA	113.00	113.00	0.00		
ACME-	J18		J-18 REQ EQ		-1 EA	50.00	-50.00	0.00		
					Parts Subtotal		138.00	0.00		

LABOUR COST	0.00	SUBLET	0.00
PARTS COST	138.00	SUBLET	0.00
REPAIR ORDER T	138.00		