
VXLAN EVPN failover validation

2 spines / 4 leaves / FortiGate active-passive HA



Reported test results / 12 of 12 passed

Same-VLAN connectivity — PASS

Hosts retained VLAN-local connectivity across the leaf fabric.

VXLAN fabric reachability — PASS

Overlay connectivity verified between participating leaf switches.

FortiGate inter-zone routing — PASS

Routed traffic passed between VLAN 10 and VLAN 20 under firewall policy.

Host LACP member loss — PASS

Dual-homed host connectivity recovered over the remaining member.

Leaf switch failure — PASS

Traffic recovered through the surviving leaf after a complete leaf shutdown.

Spine switch failure — PASS

Fabric connectivity recovered over the surviving spine path.

ECMP path redundancy — PASS

Traffic remained reachable through alternate routed fabric paths.

Firewall member link loss — PASS

An LACP aggregate stayed operational with one healthy member.

Firewall aggregate loss — PASS

Complete loss of the active firewall aggregate triggered HA failover.

Automatic FortiGate HA failover — PASS

Primary firewall shutdown triggered standby takeover and restored connectivity.

HA session synchronization — PASS

HA session-pickup and peer synchronization were verified.

Controlled manual failback — PASS

Planned role change and post-failover connectivity were validated.