SERVICE REPORT #SR-1001
Date of visit: 19 March 2025
Customer: Northwind Cold Storage
Unit: Generator GEN-328 (Asset ID A-7955)
Tech: L. Novak

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced drive belt (P/N BLT-78, qty 1) and filter (P/N FLT-56, qty 3). Tightened mounting bolts. Labor 1 hrs. Total cost $286.26. Severity: low. Recommend follow-up inspection by 10 June 2025.