SERVICE REPORT #SR-1003
Date of visit: 16 October 2025
Customer: Northwind Cold Storage
Unit: Compressor CMP-637 (Asset ID A-4999)
Tech: L. Novak

Notes:
Customer reported oil leak near the base. Technician inspected the unit and found worn components. Replaced filter (P/N FLT-36, qty 2). Recalibrated pressure sensor. Tightened mounting bolts. Labor 4 hrs. Total cost $2,010.62. Severity: critical. Recommend follow-up inspection by 16 December 2025.